


## Kelly Tillage System Field Finish Adjustments


See operators manual for detail on height adjustments. These slides are intended to help troubleshoot uneven field finish.


In principal, if there is a ridge created, the leading disc in line with that ridge is the culprit.


For furrows, the trailing disc in line with the furrow will be the culprit.


Almost always the solution is to raise the swivel at that point.











Surface profile Surface profile