


30' Chain Catch (Revision B) Page 1 of 2


It has come to our attention that in some circumstances the right hand rear chain on the 30' machine has come off of the chain carrier end while in transport. To minimize this we have put a chain catch in place to resolve this issue. Please note that all chain carriers will have holes in them but it is only the rear two that need the catch.





Assembly Update AU038

30' Chain Catch (Revision B) Page 2 of 2



New kit will include,

2x0800-360 plate

8xM12x8.8x30mm ZP Bolts (0211-1230)

8xM12 Flat washers (0231-F12)

8xM12 Nyloc Nuts (0221-NYL12)