



Technical Bulletin 037

Model 46 Walking Axle Hyper-extension

Page 1 of 2

This technical bulletin relates to Model 46 machines built before January 2018.

Under certain conditions it is possible for the rear walking axle to travel down too far resulting in the axle going over center in its travel.

The following outlines the steps required to prevent this from happening using the supplied parts:

U-bolt the supplied block as shown on the front of the center frame on both sides, this will limit the travel of the walking axle preventing hyper-extension.



