



Technical Bulletin 041

Replacement Rear Chain Catchers – Model 46

Page 1 of 1

Prior to December 2017 the Model 46 was fitted with standard rear chain catchers (part number 0810-17L). These components were shown to have insufficient adjustment, and were therefore not catching the chain as designed. New components have therefore been issued (part number 1610-17E x 2 – see below). These permit the catcher to be positioned 300mm (12”) lower than standard, which will function as intended.

The catchers should be mounted in exactly the same manner as the current components, using the fasteners currently on the machine.

