

Tariff Pricing

	2006	3009	4012	4614	6218HDX	12X	45
Front Chain							
Spiked Disc Chain 49/27/5	\$521.89	\$811.83	\$1043.78	\$1206.14	\$1623.65	\$301.54	\$1101.76
W36 Disc Chain 36/25/7	\$253.56	\$394.42	\$507.11	\$585.99	\$788.84	\$146.50	\$535.28
CL1 Disc Chain 47/35/7	\$187.65	\$298.85	\$378.78	\$437.85	\$597.70	\$1111.20	\$399.63
CL2 Disc Chain 75/25/8	\$221.90	\$325.93	\$435.13	\$497.53	\$637.93		\$440.33
Discount if CL1 is not required with CL2	\$13.90	\$24.33	\$24.33	\$24.33	\$24.33		\$24.33
CL2 Disc Chain replacement disc only	\$35.00	\$50.75	\$69.13	\$79.63	\$103.25		\$70.00
Rear Chain							
Spiked Disc Chain 49/27/5	\$536.38	\$898.81	\$1188.75	\$1362.71	\$1739.63	\$301.54	\$1246.73
W36 Disc Chain 36/25/7	\$260.60	\$436.68	\$577.54	\$662.06	\$845.18	\$146.50	\$605.72
CL1 Disc Chain 47/35/7	\$191.13	\$333.60	\$434.38	\$496.93	\$615.08	\$1111.20	\$451.75
CL2 Disc Chain 75/25/8	\$221.90	\$365.88	\$473.35	\$558.30	\$683.10		\$478.55
Discount if CL1 is not required with CL2	\$13.90	\$59.08	\$62.55	\$69.50	\$69.50		\$62.55
CL2 Disc Chain replacement disc only	\$35.00	\$51.63	\$69.13	\$82.25	\$103.25		\$70.00

