


Applies from Serial Number 2190300

Date of Change January 2019

Change Summary

0830-03 (US Only)

- Swivel balls added to centre frame pivot points
- Module mount plates deleted (move to u-bolt mounting of modules)



Replaces: n/a


Machines Affected: 30'

Assembly Manuals Changed Y



0830-10E (US only)

• Swivel balls added to rear A-frame pivot points



Replaces: n/a


Machines Affected: 30'

Assembly Manuals Changed Y



0810-28-30 (US only)

- Module mount plates modified to u-bolt configuration
- Fastener kit modified to u-bolts



Replaces: n/a


Machines Affected: 30'

Assembly Manuals Changed Y



0810-29-30 (US only)

- Module mount plates modified to u-bolt configuration
- Fastener kit modified to u-bolts



Replaces: n/a


Machines Affected: 30'

Assembly Manuals Changed Y



1646-03-1

• Swivel balls added to centre frame pivot points



Replaces: n/a


Machines Affected: Model 46

Assembly Manuals Changed Y



1610-10S-REM

• Swivel balls added to rear A-frame pivot points



Swivel balls added to rear A-frame pivot points

Replaces: n/a

Machines Affected: Model 46

Assembly Manuals Changed Y